

Date: Mon, 10 Oct 94 04:30:32 PDT
From: Ham-Space Mailing List and Newsgroup <ham-space@ucsd.edu>
Errors-To: Ham-Space-Errors@UCSD.Edu
Reply-To: Ham-Space@UCSD.Edu
Precedence: List
Subject: Ham-Space Digest V94 #286
To: Ham-Space

Ham-Space Digest Mon, 10 Oct 94 Volume 94 : Issue 286

Today's Topics:
 Webersat reception

Send Replies or notes for publication to: <Ham-Space@UCSD.Edu>
Send subscription requests to: <Ham-Space-REQUEST@UCSD.Edu>
Problems you can't solve otherwise to brian@ucsd.edu.

Archives of past issues of the Ham-Space Digest are available
(by FTP only) from UCSD.Edu in directory "mailarchives/ham-space".

We trust that readers are intelligent enough to realize that all text
herein consists of personal comments and does not represent the official
policies or positions of any party. Your mileage may vary. So there.

Date: Sun, 9 Oct 1994 18:10:29 GMT
From: tsmithers@cix.compulink.co.uk ("T W Smithers")
Subject: Webersat reception

Are there any experts out there who regularly receive Webersat A018 data.
I'm set up to receive A016 with a PSK-1T & PB and all works ok but when I
try A018 I have great difficulty in capturing any telm data.
The modem locks but it does'nt matter how carefully I tune I cannot get
any indication from the "con" led.
The same problem occurs using Weberware 1.3 capture. The system works
well with A016 so the downlink to the PC seems ok.
Any help or advice would be appreciated.

73 Trevor G0KTN / AUK 3475

tsmithers@cix.compulink.co.uk
G0KTN@amsat.org

End of Ham-Space Digest V94 #286
